HR 4342/A





Philips Domestic Appliances and Personal Care

MSH coding 8834 342 00000

PRODUCT INFORMATION

GENERAL

The HR 4342 is suitable for rooms / areas with a floor surface of up to approx. 40 m².

The air cleaner cleans the air effectively by catching 90% of the gases and 95% of the particles produced by smoking.

This is done by 3 filters:

Foam pre-filter : The foam pre - filter catches the larger

dust particles floating in the air such as

fluff and hairs.

HEPA filter HR4940: This filter takes out all smaller airborne

particles.

Carbon filter : The carbon filter with activated carbon

granulates (HR4941) effectively absorbes

the smoke gases.

This Product meets the requirements regarding interference suppression on radio and T.V.

FEATURES

Speed control: With 3 speed settings.

Safety lock: Prevents the customer from opening the front cover whilst the air cleaner is switched on.

The front cover can only be opened, if the switch has been set to the "0" position.

Over heating safety device: The overheating safety device comes into operation when the motor becomes too hot. To indicate that the appliance is still in "ON" position and connected to the mains, the pilot light remains on.

If this happens : - Switch off the motor.

- After approx. 15 min. the air cleaner can be switched on again.

TECHNICAL DATA

: 220 - 240 Volt : 60 Watts **Voltages**

Filters : 2 carbon filters

Life time filters : 3 months : carbon filters

> Hepa filter : 6 months

: 160 m³/hr Flow rate : I m² Surface filter surface

: Max. 40 m² Room / area size

Published by Philips Domestic Appliances and Personal Care

Printed in the Netherlands

© Copyright reserved

Subject to modification





POSSIBLE COMPLAINTS

I) The motor makes an irritating noise.

Check if: - The carbon filters are positioned properly in the air cleaner.

: - The filters have to be cleaned or replaced.

: - The fan has been properly fitted and can be rotated freely by hand.

2) The overheating device comes into operation.

Check : If the filters are blocked and nothing is

obstructing the air inlet and air outlet openings.

: That the fan has been fitted properly and can $% \left(1\right) =\left(1\right) \left(1\right$

rotated freely by hand.

In case these problems still remains, replace the motor (item 13) and belonging buffers (item 13A).

MAINTENANCE

Pre-filter: Wash or vacuum clean the foam pre-filter at

least every 2 months.

Fluff and /or hairs can also be removed by

using a soft brush.

Replacement filters are available under service

code 4822 480 10086

NEVER USE WET FILTERS.

HEPA filter: For a proper operation, replace this filters at

least every six months.

Replacement HEPA filters are available under type number HR 4940 and service code

4822 480 10085.


Carbon filter: Replace the carbon granules at least every

3 months.

New carbon granules are available under type

number HR 4941 and service code

4822 390 10139



PARTS LIST HR 4342/A

POS. DESCRIPTION SERVICE CODE					
I	Front cover Front cover	white grey			4822 458 10673 4822 458 10674
2	Carbon contain	o ,			4822 418 10132
3	HEPA filter HR 4940				4822 480 10085
4	Control panel	white			4822 466 12195
•	Control panel	grey			4822 466 12196
5	Switch knob	white		_	4822 310 11289
		spring		5 101	
5	Switch knob containing: s	purple/grey switch knob spring		5 101	4822 310 11302
6	Safety lock				4822 310 11291
	•	nterlock slide nterlock spring		6 102	
7	Neon assy				4822 310 10969
	•	neon light ens		7 103	
8	Rotary switch				4822 273 10367
9	Top grill	white			4822 458 10672 4822 458 10675
10	Top grill	grey			4822 458 10675
10	Front housing containing : f	•		10	4022 310 11303
		nole plug oot	(2x)	105 107	
10	Front housing	grey			4822 310 11304
	containing : f	_		10	
		nole plug oot	(2x)	105 107	
П	foam		\/		4822 480 10086
12	Fan assy				4822 310 10973
	containing : f			12	
		ock washer	ache:-	108	
		M6 shakeproof w nut M6 hex. zinc.		109	
		nut cover hexago	•	111	
13	Motor				4822 361 11162
I3A	Motor buffer				4822 310 10981
		motor mounting		112	
		retaining bracket spacer		113	
14	Back housing	white			4822 310 11305
	containing : b	_	(2)	14	
14		oot	(2x)	107	4922 210 11204
14	Back housing containing: b	grey back housing		14	4822 310 11306
	_	oot	(2x)	107	
15	Motor cover	white			4822 442 01752
15	Motor cover	grey			4822 442 01755
16	Carbon granule	es HR 4941			4822 390 10139

D.F.U. Europa 4822 736 16823 D.F.U. Rest of the world 4822 736 16864


Parts, with numbers from 100 and higher, cannot be ordered separately.

DISASSEMBLY ADVICE

remove Front cover I
remove Carbon containers 2
remove Hepa filter 3

CONTROL PANEL 4

remove Screw A-I remove Panel 4



SWITCH KNOB 5

SAFETY LOCK 6

PILOT LAMP 7

SWITCH 8

FRONT HOUSING 10

FAN 12


MOTOR 13


remove Front cover I
remove Screw A (4 x)
remove Panel 4 (See above)
remove Screw A-2
remove Front housing 10

CORDSET 114

REAR COVER 15

remove Screw C remove Cover I5





NOTE: After the product has been repaired, it should function properly and has to meet the safety requirements and legal regulations as laid down and officially established at this moment.

SCREWS: A, A-I, A-2: 3.5 x 16 (6x)

B: 3.5 x 25 (3x) C: 3.5 x 16 TRI-WING

