

Service
Service
Service

HR2096

RI2096

HR2097



Philips Consumer Life Style

Service Manual

TECHNICAL INFORMATION

- Power : 800 W
- Voltage / frequency : 220 - 240V / 50 - 60 Hz
110 V / 60 Hz
- Effective jar capacity : 1.5 L
- Capacity blender jar : 2 L
- Max jar capacity : 2 L
- Cord length : 1.0 m
- Dimensions (L x W x H) : 210 x 200 x 430 mm(product)
- Color : Stainless steel

Materials:

- Housing : SUS wrap with plastic
- Blade : Stainless steel
- Blender jar : Glass for HR/RI2096, stainless steel for HR2097

ASSEMBLY & DISASSEMBLY ADVICE

- No specific issues

REPAIR INSTRUCTION

- No specific issues

OPTIONAL (accessories)

- No specific issues

Safety

- This product meets the requirements regarding interference suppression on radio and TV.
- After the product has been repaired, it should function properly and has to meet the safety requirements as officially laid down at this moment.

Partslists

HR2096

RI2096

HR2097

Pos	12NC	Description	Remark
1	9965 100 56474	DRIVING COUPLING ASSY	
2	9965 100 64178	HOUSING (SUS WRAP)	
	9965 100 64179	HOUSING CHINA (SUS WRAP)	For HR2096/00 China version
	9965 100 64181	HOUSING BRA	For RI2096
	9965 100 64106	HOUSING TW	For HR2096/02
3	9965 100 63535	BOTTOM	
4	9965 100 56461	RUBBER FEET	
5	9965 100 56475	SAFETY LEVER	
6	9965 100 63537	MAIN PCBA(CONNECT TO KNOB PANEL)	
	9965 100 58298	MAIN PCBA LV(CONNECT TO KNOB PANEL)	For RI2096/91
	9965 100 64109	MAIN PCBA(CONNECT TO KNOB PANEL)	For HR2096/02
7	9965 100 63538	PCBA	
	9965 100 59184	PCBA LV	For RI2096/01,HR2096/02
8	9965 100 56482	MOTOR ASSY	
	9965 100 56471	MOTOR ASSY CHINA VERSION	For HR2096/00 China version
	9965 100 58297	MOTOR ASSY LV	For RI2096/01,HR2096/02
9	9965 100 56481	KNOB PANEL WEU	
	9965 100 56477	KNOB PANEL CHINA VERSION	For HR2096/00 China version
	9965 100 64107	KNOB PANEL TW	For HR2096/02
10	9965 100 56462	INTERLOCK SUPPORT + WIRE	
11	9965 100 61615	SPATULA	
12	9965 100 56473	MEASURING CUP	
13	9965 100 56467	JAR LID	For HR2096/RI2096
	9965 100 59678	JAR LID	For HR2097
14	9965 100 61668	COLLAR	For HR2096/RI2096
	9965 100 61776	COLLAR	For HR2097
15	9965 100 61616	KNIFE UNIT JAR AND SEALING RING	
16	9965 100 60779	XBJ GLASS JAR FOR HR2095/2096	See page 3 for where it using for
	9965 100 60781	DALONG GLASS JAR FOR HR2095/2096	See page 3 for where it using for
	9965 100 59681	STAINLESS STEEL JAR	For HR2097
17	9965 100 56483	POWER CORDSET VDE	For HR2096/2097
	9965 100 56468	POWER CORDSET CHINA VERSION	For HR2096/00 China version
	9965 100 56599	POWER CORDSET 3PIN	For HR2096/01
	9965 100 58302	POWER CORDSET AUS	For HR2096/03
	9965 100 58296	POWER CORDSET BRA	For RI2096
	9965 100 61614	POWER CORDSET SWITZLAND	For HR2096/04
	9965 100 64108	POWER CORD TW	For HR2096/02
	9965 100 64394	POWER CORDSET KOREA	For HR2096/00 Korea version
18	9965 10056472	TOP COVER	

Country list : which country will use what kind of glass jar

	XBJ Glass Jar	Dalong Glass jar
Germany	Y	
France	Y	
Iberia	Y	
Italy	Y	
Benelux	Y	
Nordic	Y	
Chili Santiago		Y
CE Iquique		Y
Dubai	Y	
Peru		Y
Uruguay		Y
Chile		Y
Poland	Y	
Russia	Y	
CEE	Y	
Ukarine	Y	
Hong Kong	Y	
UK	Y	
Thailand		Y
Malaysia		Y
Singapore		Y
Taiwan	Y	
Australia	Y	
Switzerland	Y	
China	Y	
South Korea		Y
Brazil	Y	

Main unit view

HR2096
RI2096
HR2097

1



2



3




4




5



6



7



8



9



10



17



18



Accessorry view

HR2096

RI2096

HR2097

11



14(right for HR2097)



12




15



13(right for HR2097)



16(right for HR2097)



Revision list

HR2096

RI2096

HR2097

1. Version A : Initial release.
2. Version B : Adding HR2096/03,RI2096.
3. Version C : Correct the supplier's error about the factory code of position 7, so the part 12NC updated.
4. Version D : Add HR2097
5. Version E : Glass jar source change to XBJ and Dalong, and add country list for which country use what kind of glass jar.
6. Version F : Update spatula and knife unit, old and new ones are interchangeable, and update collar, also add powercord for HR2096/04 Switzerland.
7. Version G : Update base cover cord hole. also update PCBA and MAIN PCBA which old and new are interchangeable.
8. Version H : Update flange add on three button holes to avoid button jammed issue. All old housing are deleted and change to new housing.
9. Version I : Add HR2096/02 TW version.
10. Version J: Add HR2096/00 Korea version.